

CERTIFICATE

Welding of railway vehicles and components according to:
EN 15085-2

This Certificate is issued to: **CASPLE, S.A.**
C/ Alcalde Martin Cobos, 2
(09007) Burgos, Spain.

Is qualified to perform welding work within the range of certification of

Certification Level CL1 according to EN 15085-2:2020+A1:2023
Type of activity: P

Type of components: New build of railway vehicles and their components

Welding processes and base material groups:

Welding processes according to EN ISO 4063	Base material group to CEN ISO/TR 15608	Dimensions	Comments
135	1.2, 2.2 2.2	t = 3-12 mm t = 3-12 mm	BW/FW BW/FW, automatic

Responsible welding coordinator (RWC): Alberto Rodríguez (CSR – Level A) born: 1971
Deputy welding coordinator (DWC): Victor Remiro (CSS – Level C) born: 1989
Comments: see reverse.

Certificate No: LRQA/15085/CL1/0259/22/1

Valid: from 16 June 2025 to 15 June 2028

Issued on: 16 June 2025

Auditor: Aitziber Gorriño-Beaskoa (IWE number: ES-1722)

Juan Antonio Pozo – Head of MCB

General regulations (see annex)

Annex certificate No: LRQA/15085/CL1/0259/22/01

CASPLE, S.A.

C/ Alcalde Martin Cobos, 2
(09007) Burgos, Spain.

Comments:

This Certificate is subject to monitoring of compliance by LRQA Iberia Inspection S.A. as required by the standard EN 15085-2:2020+A1:2023.

Company assessed as small manufacturer in accordance to EN15085-2 Annex C.

Company assessed for a maximum of CPC2.

The welding coordinator Alberto Rodriguez (RWC) is entitled to test welders/operators and PQRs in accordance with the relevant standards within the scope of this certificate.

General regulations

according to EN 15085-2:2020+A1:2023

Revocation of the Certificate

The manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated Standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate,

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body. If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least three months before the end of the period of validity of the current certificate.

Distribution list:

1. Applicant (original- Email)
2. LRQA Inspection Iberia Madrid